
Types of Parameters Measured FTIR and NIR in Dairy Products

Added water, butterfat, casein, citric acid, density, free fatty acids, lactose, moisture, protein, nonfat solids, nonprotein nitrogen/calculated urea, other carbohydrates, pH, salt, total solids, solids nonfat, true protein
